

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

JV1359
NNE
> 1
1.718 mi.
9069 ft.

MANHOLE 38245
KINGS HIGHWAY / E 2ND ST
BROOKLYN, NY

NY Spills S104194752
N/A

Site 1 of 2 in cluster JV

Relative:
Higher

Actual:
24 ft.

SPILLS:

Name: MANHOLE 38245
Address: KINGS HIGHWAY / E 2ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9906732 / 2002-01-28
Facility ID: 9906732
Facility Type: ER
DER Facility ID: 252682
Site ID: 313376
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1999-09-07
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-09-07
CID: 312
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-09-07
Spill Record Last Update: 2004-11-03
Spiller Name: Not reported
Spiller Company: CON EDISON

Spiller Address: 4 IRVING PLACE
Spiller Company: 999
Contact Name: Not reported
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT e2mis no. 127616: 9/7/99 02:45HRS-A. WALKER-33596-SEN FLD
OPER.-FOD-WHILE AT LOCATION TO WORK ON FDR 7B40-FOUND LESS THAN 1
PINT DIELECTRIC FLUID ON LESS THAN 1 PINT OF WATER COMING FROM CABLE
JOINT-IN MH 38245-S/S KINGS HIGHWAY 33' E/O E 2 STREET-APPEARS
CONTAINED AT THIS TIME-NO SEWER CONNECTIONS OR SUMP-NO SEWERS OR
WATERWAYS AFFECTED. NO OUTSIDE IMPACT-NO OTHER OIL FILLED EQUIPMENT
IN STRUCTURE-TOOK A LIQUID SAMPLE-PLACED ENV TAG 15576-METERED
PARKING..CLEANUP PENDING LAB RESULTS. UPDATE***** 09-08-99 22:45HRS.
9 MADE REPAIRS TO JOINT AND CLEANUP WAS COMPLETED. STRUCTURE DOUBLE
WASHED AND TAG# 15576 REMOVED. STRUCTURE CLEANED BY F. DELLATORRE -
48634 - ENV. OPS. AS 50 - 499. LAB RESULT RECEIVED 9/9/99 - 1430.
99-09276. 43 PPM."

Remarks: "1QRT SPILLED ON 1 PINT OF WATER - CASE #127616 - SAMPLE TAKEN - STEVE
SANGESLAND CONTACTED"

All Materials:

Site ID: 313376
Operable Unit ID: 1085163
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID: 299454
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported